

THE FOLLOWING IS FOR INFORMATION ONLY:

There are no gravity zones established in France for the regulation about NAWI and there are no requirements for zone stickers.

Manufacturers have the responsibility for bringing instruments within the maximum permissible errors for new instruments at the place of use.

To achieve this the new gravity concept as described in WELMEC guide 2 is accepted in France.

Manufacturers may also define their own zones according to their marketing organisation.