

THE FOLLOWING IS FOR INFORMATION ONLY:

No formal gravity zones have been established in Slovakia for NAWI.

There are no formal requirements for gravity zone markings.

Manufacturers have the responsibility for bringing new instruments within the MPE at the place of their use.

WELMEC approach (as defined in the "Gravity zones" section of the WELMEC 2 guide) is accepted.